

SAFETY RULES TO BE FOLLOWED ON THE SITE

A. GENERAL & CLOTHING

1. ALL CONSTRUCTION WORKERS SHALL WEAR OVER-ALLS, SAFETY SHOES AND HARD HATS WHEN WORKING WITHIN THE PREMISES OR OUTSIDE THE WORK AREA.
2. EYE GLASSES TO BE WORN WHILE CUTTING METAL, STONE AND SUCH MATERIALS.
3. WHILE DOING WET WORK OR HAZARDOUS ACTIVITIES IT IS COMPULSORY FOR WORKERS TO WEAR PROPER HAND GLOVES.
4. THE SITE TO HAVE PROPER GENERAL LIGHTING AND GOOD GENERAL VISIBILITY IN ALL AREAS.

B. COOKING AND STAYING ON SITE

1. COOKING AND USING THE SITE, AS LABOUR ACCOMODATION IS NOT ALLOWED.

C. SANITARY ARRANGEMENTS

1. TOILETS/URINALS/ SHALL BE SEPARATELY ARRANGED OUTSIDE THE SITE. EACH CONTRACTOR WILL BE DESIGNATED THEIR OWN CUBICLES. THE CONTRACTOR SHALL EMPLOY ONE OF HIS STAFF TO KEEP THE CUBICLE CLEAN AT ALL TIMES
2. NO WASHING OF CLOTHES OR UTENSILS & LITTERING ON THE SITE SHALL BE ALLOWED.

D. STORAGE OF MATERIALS

1. STORAGE OF MATERIALS LIKE GLASS, STONE SLABS, METAL SHEETS, ETC SHALL BE DONE IN A SUCH A MANNER, WHICH IS NOT INJURIOUS TO ANYBODY WORKING ON SITE.
2. CONTRACTORS RESPONSIBLE FOR THE MATERIAL TO DESIGNATE A STAFF MEMBER TO OVERSEE AND RELEASE MATERIAL WHENEVER REQUIRED
3. IT WILL BE THE LIABILITY OF THE CONTRACTOR IF ANY OF HIS MATERIALS IS MISSING. THE CONTRACTOR WILL COMPENSATE AND REPLACE THE MISSING MATERIAL AT HIS OWN COST

E. HAZARDOUS MATERIALS

1. ANY SPRAYING / MELTING OR STORAGE OF HAZARDOUS OR INFLAMMABLE MATERIALS SHALL NOT BE ALLOWED ON SITE.
2. INSULATION MATERIAL LIKE GLASSWOOL ETC SHALL BE STORED AS PER STANDARDS WITH MINIMUM CONTAMINATION OR EXPOSURE TOWARDS HUMAN BEINGS.

G. DEBRIS REMOVAL & CLEANING

1. NO DEBRIS SHALL BE ALLOWED TO PILE UP IN THE SITE OR OUTSIDE THE SITE AREAS. TWICE DAILY CLEANING SHALL IS COMPULSORY SO AS TO HAVE THE SITE CLEAN IF ANY EMERGENCIES ARISE. ALL DEBRIS TO BE STORED IN PROPER INDUSTRIAL BINS BEFORE PASSING TO A SKIP FOR REMOVAL TO A

DUMPING YARD. THE CONTRACTOR WILL BE RESPONSIBLE TO PROVIDE HIS OWN SKIP AND DUSTBINS AND REMOVAL OF ALL WASTE FROM SITE.

2. NO METAL, GLASS, STONE, TILES, OR SHARP OBJECTS TO BE LEFT UNSUPERVISED. ONCE THE JOB IS OVER THESE SHARP OBJECTS TO BE MOVED OUT CAREFULLY. THE CONTRACTOR WILL BE LIABLE FOR ANY ACCIDENTS ARISING OUT OF THIS CONDITION.
3. ALL DEBRIS REMOVAL FROM THE SITE SHALL BE DONE REGULARLY WHEN THE SKIP IS FULL AND AS PER LOCAL AUTHORITY RULES.

H.SCAFFOLDING & RAILINGS, WORK AT HEIGHTS

1. ALL SCAFFOLDINGS SHALL BE SECURED PROPERLY ANCHORED WHILE WORKING AT HEIGHTS. SAFETY BELTS ARE COMPULSORY AND SHALL BE USED AT ALL TIMES DURING THE WORK PROCESS. ALL SCAFFOLDING RIGS TO HAVE CLEARANCE CERTIFICATES FROM THE CONTRACTOR. THE CONTRACTORS SUPERVISOR TO REGULARLY CHECKS THE SCAFFOLDING UNIT BEFORE COMMENCEMENT OF WORK.
2. ALL BARE STAIRCASE OPENINGS, DUCTS SHALL BE FITTED WITH A TEMPORARY RAILING AROUND IT AND THEN SEALED WITH RED COLOURED SEALANT TAPE.
3. ALL HANGING POINTS TO BE CERTIFIED BY A STRUCTURAL ENGINEER BEFORE ANY MATERIAL IS HUNG OF IT. ONCE AN INSTALLATION IS COMPLETED, THE CONTRACTORS SUPERVISOR TO CHECK AND ISSUE CERTIFICATE OF CLEARANCE.

I.ELECTRICAL WORK

1. NO ELECTRICAL POWER CONNECTIONS SHALL BE MADE WITH TWISTED WIRES. ONLY SHEATHED CABLES WITH PROPER EARTHED PLUG PINS TO BE USED WITH TEMPORARY SWITCH BOXES. IF ANY OF THE SWITCH BOXES ARE BROKEN OR CRACKED THEY WILL HAVE TO BE REPLACED.
2. ALL WIRE JOINTS TO BE CONNECTED USING STANDARD PLASTIC CONNECTORS. THE CONNECTORS TO HAVE PROPER INSULATION TAPE COVERS.
3. CONTRACTORS TO HAVE A DAILY CHECK ON ALL POWER CABLES AND SOCKET. A DAILY REPORT TO BE MADE AND CLEARANCE CERTIFICATES ISSUED APPROVING OF ALL ELECTRICAL CONNECTIONS AT SITE.
4. GENERATORS SHALL BE SECURE WITH PROPER CABLING AND EARTHING.
5. PROPER PROCEDURES SHOULD BE UNDERTAKEN BEFORE STARTING A GENERATOR.
6. THE CONTRACTEE TO CHECK SITE PERIODICALLY TO ENSURE THE AREA IS WORKABLE AND FREE OF TRAPS. ALL ISSUES WILL BE BROUGHT TO THE NOTICE OF THE CONTRACTOR WHO WILL BE OBLIGATED TO RECTIFY OR CHANGE AS PER INTERNATIONAL STANDARDS.

J.WATER & LEAKAGES

1. NO WATER LOGGING SHALL BE ALLOWED ON SITE.
2. ANY LEAKAGES SHALL BE BROUGHT TO THE SUPERVISOR'S NOTICE IMMEDIATELY AND RECTIFIED. IF THE SUPERVISOR NOTICES A LEAKAGE THEN HE WILL HAVE TO FOLLOW PROPER PROCEDURE BY PUTTING OFF THE EXISTING ELECTRICAL FEED AND THEN CHECKING TO FIND THE SOURCE OF THE LEAK. A REPORT WILL HAVE TO BE MADE AND PASSED ON TO THE CONTRACTEE WHO WILL DECIDE ON CORRECTIVE ACTION.
3. ALL DRAIN PIPES TO BE CERTIFIED AND TESTED BEFORE COMMISSIONING. THE CONTRACTOR TO GET CLEARANCE FROM THE CONTRACTEE BEFORE STARTING THE BUILD.

K.FIRE SAFETY

1. FIRE EXTINGUISHERS (DRY POWDER TYPE) FOR **ABC** TYPE OF FIRES SHALL ALWAYS BE KEPT READY FOR USE AT ALL AREAS OF THE SITE. ALL STAFF AND LABOUR TO BE TRAINED IN USAGE OF THESE EXTINGUISHERS.
2. ALL FIRE EXTINGUISHERS TO BE TESTED REGULARLY AND CERTIFIED BY THE CIVIL DEFENSE.
3. IN CASE OF FIRE THE ESCAPE ROUTE, SHALL ALWAYS BE KEPT CLEAR OF OBSTACLES & DEBRIS. ALL CONTRACTORS TO NOTIFY AND CONDUCT A DRILL WITH STAFF WORKING AT THE SITE. THE ESCAPE ROUTE AND ASSEMBLY POINT SHALL BE MARKED WITH ARROWS AND ILLUMINATED EXIT SIGN BOXES.
4. ALL PLASTIC AND PLYWOOD SHEETS TO BE AFFIXED FIRMLY WITH FASTENERS TO PROTECT THE CONCERNED AREAS AS WELL AS ALLOW FOR EASY MOVEMENT IN TIMES OF AN EMERGENCY.
5. THE AREA TO BE CLEARED OF ALL HAZARDOUS MATERIALS BEFORE THE COMMENCEMENT OF THE WELDING ACTIVITY. WHILE WELDING, THE CONCERNED STAFF TO BE PROPERLY DRESSED AND WELL PROTECTED. PROPER CERTIFIED PROTECTIVE GLASSES TO BE USED.
6. ALL CYLINDERS AND PIPES TO BE CERTIFIED AND LEAKPROOF. THE CONTRACTOR TO HAND OVER TO CONTRACTEE THE CLEARANCE CERTIFICATE BEFORE COMMENCEMENT OF ACTIVITY.
7. NO SMOKING STRICTLY ON SITE.

L.MACHINERY

1. ALL MACHINERY & POWER TOOLS SHALL BE PROPERLY EARTHED.
2. NO MACHINERY & POWER TOOLS SHALL BE LEFT CONNECTED AND UNATTENDED OR IN A MANNER WHICH CAN HARM OTHERS WORKING ON SITE.
3. ALL ELECTRICAL CONNECTIONS SHALL BE REMOVED WHEN THE MACHINES ARE CLOSED DOWN.
4. INFERIOR QUALITY OR WORN OUT TOOLS, SHALL NOT BE BROUGHT AND ALLOWED ON SITE.

PURPLE FIRE INTERNATIONAL LLC

[Annexure – IV]

5. THE CONTRACTOR TO CERTIFY ALL TOOLS AND MACHINERY BROUGHT TO SITE

M. INJURY AND ACCIDENTS

1. CONTRACTORS TO INSURE THE JOB CONTRACT AND WORKERS WORKING ON SITE.
2. IN CASE OF ACCIDENT OR INJURY THE CONTRACTOR TO DESIGNATE A STAFF MEMBER TO ADMINISTER FIRST AID BEFORE MOVEMENT OF VICTIM TO A HOSPITAL OR DOCTOR.
3. THE SITE TO HAVE A FIRST AID BOX SET UP BY THE CONTRACTEE AND ALL CONTRACTORS TO BE INFORMED OF ITS LOCATION.
4. EACH CONTRACTOR TO REGISTER A DAILY RECORD OF WORKERS ENTRY AND EXIT FROM SITE. ALL SUPERVISORS TO KEEP REGISTERS READY FOR INSPECTION BY THE CONTRACTEE ON SITE.